



Tandler Gearbox Retrofit

TIP Z024-0001

G a e P i l Deck

Benefits:

- This improvement replaces obsolete gearboxes with commercially available units.



Revised Design

Original Design

Tandler Gearbox Retrofit

Ze a d G a l e P i l Deck

This simi eme l eplace the e i i g b e le.e gea b e i.h e c mme icall a ailable Ta dle gea b e

This simi eme i i cl de e e l e l e b e c l i g a d m l e f the gea b e



Tandler Gearbox Retrofit

Included in this TIP:

All required materials
Necessary engineering
Updated drawings and change of electrical connections

Estimated downtime, no production:

10 days

Estimated startup, limited production:

3 days

Estimated monitoring in production:

3 days

Required manpower:

1 BW Partner Service Mechanical Field Service Engineer
1 BW Partner Service Electrical Engineer
Additional Assistance from Customer Maintenance
(Additional local resources to be determined, if needed)

How can we help you? Please do not hesitate to contact us for any questions regarding our comprehensive Customer Service offerings:

TIP Upgrade

Please email at tip@tandler.com